

Meriedweg 11
CH-3172 Niederwangen
Switzerland
info@netmodule.com
http://www.netmodule.com

http://www.netmodule.com Tel +41 31 985 25 10 Fax +41 31 985 25 11

# Release Note NRSW 4.0.0.101

Project Name: NRSW 4.0

#### **Abstract:**

This document represents the release note for NetModule Router Software 4.0.0.101. It informs on new functionality, corrections and known issues of the current software version of NetModule's router series.

# **Keywords:**

NetModule, Software Development, NRSW, Release Note

#### **Document Control:**

Document:	Version	1.0
	File	NRSW-RN-4.0.0.101

Status Valid

 Role
 Name

 Author
 Benjamin Amsler

 Review
 Stefan Schlosser

Approval Role Name
Technical CEO Thomas Siegrist



## 1 Release Information

#### **NetModule Router Software:**

Version: 4.0.0.101

Date: August 28, 2016

#### **Supported Hardware:**

NetModule Router	Hardware Versio
NB1600	V1.0 - V3.3
NB2700	V1.0 - V2.7
NB2710	V1.0 - V2.7
NB2800	V1.0 - V1.1
NB3700	V2.0 - V4.3
NB3701	V1.0 - V1.3
NB3710	V2.0 - V4.3
NB3711	V1.0 - V1.3
NB3720	V2.0 - V4.3
NB3800	V1.0 - V1.3

### **Unsupported Hardware:**

#### **NetModule Router**

NB1300 Series

NB2200 Series

NB2300 Series

NB2500 Series

NB2600 Series



#### **NetModule Insights**

Subscribe to our mailing and get the latest news about software releases and much more



# 2 New Features

Case-#	Description
40834	Configurable IP-Passthrough Network It is now possible to configure the WAN network which will be passed-through to a LAN host and to communicate with other devices in that network.
41319 43177	Firmware Update on NB2800/NB3800 Firmware updates can now be run on NB2800/NB3800.
43079	SDK Workdays/Weekend Triggers Triggering scripts only on workdays or weekend is now possible.



# 3 Fixes

The following issues and problems have been fixed.

Case-#	Description				
43102	Flipping WAN Links				
	It was not possible to flip configured WAN links using the Web Manager. This has been fixed.				
41681	Preferred Service on Sierra MC7455				
	The preferred service was not achieved on Sierra MC7455. This is working now.				
43144	System Time over GPS				
43128	The system has not been notified in case the time has been synchronized over GPS. This has be fixed.				
42971	QoS Issues				
43100	The QoS page showed no configurable interfaces. The daemon is now also more robust in case of a bogus configuration.				
43205	TCP Challenge ACK				
	The kernel has been patched to make TCP challenge ACKs less predictable (see CVE-2016-5696).				
43263	SMS Filtering				
	It appeared that all messages have been filtered out although a rule existed which should have allowed messages from a particular number. This has been fixed.				
43268	Invalid Signal Information on Huawei EM820W				
	Under some circumstances it appeared that the retrieved RSCP/ECIO value was declared as invalid on Huawei EM820W. This has been fixed.				
42778	Force DHCP Static Address for Ethernet Port				
42797	The DHCP server has assigned a new address out of the lease pool and not the configured static address if a new device has been attached to the corresponding Ethernet port. This has been fixed.				
43241	SNMP Upload				
	Uploading the configuration or system log via SNMP failed due to a bogus URL check. This has been fixed.				
43275	GLONASS on Huawei ME909				
	Receiving information from GLONASS satellites was not working. This has been fixed.				
43136	USSD Queries				
	USSD queries were not working on all modems. They have been verified for the following modems:				
	Option GTM661/GTM671				
	Huawei EM820				
	Huawei ME909				
	Sierra MC7710				



# 4 Known Issues

Items listed here represent minor problems known at release time. These issues will be resolved in a later version.

Case-#	Description
32507	No VRRP on Bridged Interfaces VRRP over bridged interfaces is not implemented.
36992	No SMS Delivery Reports SMS delivery reports are currently not possible with Option GTM661/GTM671, Huawei EM820 and Sierra MC7710 modems.
42851	No RSTP on Bridged TAP Devices RSTP does not work on bridged TAP devices.



# 5 Pitfalls

Items listed as pitfalls are potential problems that may arise because of specific environmental conditions. There are currently no fixes planned for these issues.

Case-#

Description



#### **6 OSS Notice**

We inform you that NetModule products may contain in part open source software. We are distributing such open source software to you under the terms of GNU General Public License (GPL)<sup>1</sup>, GNU Lesser General Public License (LGPL)<sup>2</sup> or other open source licenses<sup>3</sup>.

These licenses allow you to run, copy, distribute, study, change and improve any software covered by GPL, Lesser GPL, or other open source licenses without any restrictions from us or our end user license agreement on what you may do with that software. Unless required by applicable law or agreed to in writing, software distributed under open source licenses is distributed on an "AS IS" basis, WITHOUT WARRANTIES OR CONDITIONS OF ANY KIND, either express or implied.

To obtain the corresponding open source codes covered by these licenses, please contact our technical support at router@support.netmodule.com.

Release Note NRSW 4.0.0.101

<sup>&</sup>lt;sup>1</sup>GPLv2 license is available at http://www.gnu.org/licenses/gpl-2.0.txt

<sup>&</sup>lt;sup>2</sup>LGPL license is available at http://www.gnu.org/licenses/lgpl.txt

<sup>&</sup>lt;sup>3</sup>OSI licenses (ISC License, MIT License, PHP License v3.0, zlib License) are available at http://opensource.org/licenses



#### 7 Change History

Version	Date	Name	Reason	
1.0	2016-08-28	amsler	Release	

#### Copyright © 1998 - 2016 NetModule AG; All rights reserved

This document contains proprietary information of NetModule AG. No part of the work described herein may be reproduced. Reverse engineering of the hardware or software is prohibited and is protected by patent law. This material or any portion of it may not be copied in any form or by any means, stored in a retrieval system, adopted or transmitted in any form or by any means (electronic, mechanical, photographic, graphic, optic or otherwise), or translated in any language or computer language without the prior written permission of NetModule AG.

The information in this document is subject to change without notice. NetModule AG makes no representation or warranties with respect to the contents herein and shall not be responsible for any loss or damage caused to the user by the direct or indirect use of this information. This document may contain information about third party products or processes. This third party information is out of influence of NetModule AG therefore NetModule AG shall not be responsible for the correctness or legitimacy of this information. If you find any problems in the documentation, please report them in writing by email to info@netmodule.com at NetModule AG.

While due care has been taken to deliver accurate documentation, NetModule AG does not warrant that this document is error-free.

"NetModule AG" and "NetModule Router" are trademarks and the NetModule logo is a service mark of NetModule AG.

All other products or company names mentioned herein are used for identification purposes only, and may be trademarks or registered trademarks of their respective owners.

The following description of software, hardware or process of NetModule AG or other third party provider may be included with your product and will be subject to the software, hardware or other license agreement.

NetModule AG is located at:

Meriedweg 11 CH-3172 Niederwangen Switzerland

info@netmodule.com

Tel +41 31 985 25 10 Fax +41 31 985 25 11

For more information about NetModule AG visit the NetModule website at www.netmodule.com.