



Maulbeerstrasse 10 CH-3011 Bern Switzerland info@netmodule.com www.netmodule.com Tel +41 31 985 25 10 Fax +41 31 985 25 11

Release Notes - NRSW 4.6.0.109

Project Name: NRSW

Abstract:

This document represents the release note for NetModule Router Software 4.6.0.109. It informs on new functionality, corrections and known issues of this software version of NetModule's router series.

Keywords:

Netmodule AG, Software Development, NRSW, Release Notes

Document Control:

Document:	Version	1.0
	File	NRSW-RN-4.6.0.109
	Status	Final
Own at it was		
Creation:	Role	Name
	Author	Felix Kopf
	Review	Matthias Fricker
Approval	Role	Name
	Director Product Development	Benjamin Amsler

NET MODULE

1 Release Information

NetModule Router Software:

Version:	4.6.0.109
Date:	Feb 06, 2025

Supported Hardware:

NetModule Router	Hardware Version
NB800	V2.0 - V2.2, V3.2 (Rev.B02 - B03)
NG800	V3.0 - V3.2
NB1601	V1.0 - V1.7
NB1800	V2.4 - V2.6
NB1810	V2.4 - V2.6
NB2800	V1.0 - V1.4
NB2810	V1.2
NB3701	V1.0 - V1.10
NB3800	V1.0 - V1.10

Unsupported Hardware:

NetModule Router

NB1300 Series NB1600 Series NB2200 Series NB2500 Series NB2600 Series NB2700 Series NB3700 Series NB3711

NetModule Insights

Subscribe to our mailing and get the latest news about software releases and much more





2 Security Fixes

The following security relevant issues have been fixed.

Case-#	Description
577010	RADIUS fixes CVE-2024-3596: The RADIUS protocol had a vulnerability that potentially made it susceptible to forgery attacks, which could modify the Access-Accept or Access-Reject RADIUS response, this is fixed.



3 Fixes

The following issues and problems have been fixed.

457860 LXC fixes LXC DNS setting would remain if the container was deleted. This is fixed. 549020 Recovery improvments In the recovery image for TimeServer the web interface was not available. This is fixed.	
In the recovery image for TimeServer the web interface was not available. This is f	
	fixed.
568811 BGP fixes In some cases, BGP packets were not properly routed via WWAN interfaces if up configuration from an older NRSW version. This is fixed.	pdating an existing



4 Discontinued Features

The following Features were discontinued.

Case-#	Description	
605635	Removed RADIUS for web-UI login for certain hardware platforms Web-UI user login via RADIUS authentication will no longer be available on NB1600, NB2700, NB37x0 for security reasons regarding CVE-2024-3596.	



5 OSS Notice

See User Manual Chapter OSS.

6 Change History

Version	Date	Name	Reason
1.0	Feb 06, 2025	Felix Kopf	Final version

Copyright © 1998 - 2025 Netmodule AG. All rights reserved

The performance features described here are binding only if they have been expressly agreed when the contract was made. This document was produced by Netmodule AG according to the best of the company's knowledge. Netmodule AG reserves the right to change the contents of this document without prior notice. Netmodule AG can give no guarantee in respect of the correctness or accuracy of the information in this document.

Netmodule AG can accept no responsibility for damages, resulting from the use of the network components or the associated operating software. In addition, we refer to the conditions of use specified in the license contract.

Netmodule AG is located at:

Maulbeerstrasse 10 CH-3011 Bern Switzerland info@netmodule.com Tel +41 31 985 25 10 Fax +41 31 985 25 11

For more information about Netmodule AG visit the website at www.netmodule.com.